

Memorandum

11300
MAIN

DATE: 18 JUL 1985

FROM: Base Maintenance Officer

TO: Assistant Chief of Staff, Facilities

SUBJ: GOLF COURSE WATERING

Thanks, Bill
This is a good
idea + we should
push hard.
Bill

1. We have attempted to identify the water distribution system at the Golf Course. Due to the numerous groups who have worked on the system, including Maintenance and Special Services forces, as well as troops in training projects, the drawings are extremely outdated. We are requesting assistance from the Public Works Office to update the layout drawings.

2. When the drawings are updated, we can attempt to isolate the clubhouse and come up with a plan for watering the course with nonpotable water. They currently have two 250 GPM booster pumps to provide pressure for the pop-up sprinklers on the north course which, when operating, do draw a considerable amount of water. We really need to pursue this.

W. M. RICE

CLW

0000001278

ROUTING SLIP

	ACTION	INFO	INITIAL
BMO			
ABMO			
ADMIN			
F&A			
MAINT NCO			
M&R			
OPNS			
PROP			
UMACS			
UTIL	✓		
SECRETARY			

COMMENTS:

*Let's proceed with info and
get info from PWO. When do you
think will have the information?
WMP*

CLW

0000001279